



Comment: 6/12V 20/40/10 amp; 200 amp crank assist.

Part #	Raw Mat #	Description	WD Cost	List Cost
605671		Front Leg	\$0.00	\$0.00
605672		Wheel w/nuts (2)	\$0.00	\$0.00
605675		Charge Rate Switch	\$0.00	\$0.00
610052		Axle w/nuts	\$0.00	\$0.00
610054		Base panel	\$0.00	\$0.00
610695		Ammeter	\$0.00	\$0.00
610696		AC power cord	\$0.00	\$0.00
610753		Handle	\$0.00	\$0.00
610895		Timer w/knob	\$0.00	\$0.00
610977		Back panel	\$0.00	\$0.00
611002		Rectifier	\$0.00	\$0.00
611006		DC cable set	\$0.00	\$0.00
611020		Transformer	\$0.00	\$0.00
611021		Voltmeter	\$0.00	\$0.00
611022		Switch	\$0.00	\$0.00
611023		Front panel	\$0.00	\$0.00
611024		Side panel	\$0.00	\$0.00
611025		Top panel	\$0.00	\$0.00
611028		DC circuit breaker (1)	\$0.00	\$0.00