



Comment: needs to be factory serviced (not ARS) unless out of country

Part #	Raw Mat #	Description	WD Cost	List Cost
	037-0579	Wire Diagram	\$0.00	\$0.00
	027-0670	Manual	\$0.00	\$0.00
	017-0062	Bushing-Strain Relief	\$0.00	\$0.00
	044-0178	Transformer assy	\$0.00	\$0.00
	132-0071	PC Board	\$0.00	\$0.00
	A-1490528	Amp Meter	\$0.00	\$0.00
	A-1591014	Switch; 13a 125v	\$0.00	\$0.00
	A-2-133344	Circuit Breaker; 12v 20a	\$0.00	\$0.00
	A-5-1320517	AC Cord 18/3 6ft	\$0.00	\$0.00
	A-83986	DC Leads 16/2 7ft	\$0.00	\$0.00
	D-122532	Panel; Side/Top/Side	\$0.00	\$0.00
	D-34-122599	Panel; Front/Bottom/Back	\$0.00	\$0.00
	030-0569	Carton; 10-1/8 X 6-1/4 X 8	\$0.00	\$0.00