



Comment: thermal fuse in yellow wire to transformer primary is not shown.

Part #	Raw Mat #	Description	WD Cost	List Cost
610242		Thermal Fuse	\$0.00	\$0.00
605671		Front leg	\$0.00	\$0.00
605672		Wheels w/nuts (2)	\$0.00	\$0.00
605213		Handle	\$0.00	\$0.00
604579		Stop/Go Lite	\$0.00	\$0.00
610189		Fan Blade	\$0.00	\$0.00
610190		Fan Motor	\$0.00	\$0.00
605206		AC Cord	\$0.00	\$0.00
605675		Switch w/knob	\$0.00	\$0.00
605677		DC Cable Set	\$0.00	\$0.00
610069		DC Circuit Breaker (1)	\$0.00	\$0.00
610287		Axle w/nuts	\$0.00	\$0.00
610188		Transformer	\$0.00	\$0.00
610418		Rectifier (also need resistor 145-0096, 680ohm 1	\$0.00	\$0.00
610389		Timer w/knob	\$0.00	\$0.00
610324		Amps Charge Meter	\$0.00	\$0.00
6202		Clamps (1 pair, includes jaws)	\$0.00	\$0.00
6204		Jaw Kit (repairs one clamp)	\$0.00	\$0.00
610456		Front/Back/Base Panel	\$0.00	\$0.00
610286		Top/Side/Side Panel	\$0.00	\$0.00
603147		Pointer Knob	\$0.00	\$0.00
			\$0.00	\$0.00