


## WIRING DIAGRAM



### MODEL 6015 PARTS LIST DARK BLUE CABINET

605206	AC CORD	610254	FEET
605632	AMPS CHARGE METER	610281	DC CIRCUIT BREAKER
605675	SWITCH W/KNOB	610288	DC CABLE SET
610054	BASE	610289	THERMAL FUSE
610057	HANDLE	610344	RECTIFIER ASSY
610071	SIDES	610345	TRANSFORMER
610074	TOP	610352	FRONT/BASE/BACK
610189	FAN BLADE	610389	TIMER
610190	FAN MOTOR		