



Comment: 12 Volt - 10 Amp Automatic Charger

Part #	Raw Mat #	Description	WD Cost	List Cost
	027-0677	Manual	\$0.00	\$0.00
610615		DC Cord & Clamps	\$0.00	\$0.00
610617		Circuit Board	\$0.00	\$0.00
610619		Handle	\$0.00	\$0.00
610622		Stand-Off (4)	\$0.00	\$0.00
610623		Circuit Breaker	\$0.00	\$0.00
610937		Transformer	\$0.00	\$0.00
610945		AC Cord	\$0.00	\$0.00